

Issue List

- EF-1 Conduit Box Cover Missing
- EF-2 Back Draft Damper Obstruction



10-02-23 ARBY'S 2010 - PURCELL, OK

Project Issue Information

Issue Name : EF-1 Conduit Box Cover Missing
Description : EF-1 for Hood missing electrical conduit box cover. Leaving wiring exposed to climate conditions.
Created By : National TAB **Assigned To :** National TAB - Wale Odofin
Status : Open
Originated Date : 10/03/2023 - Darius Payne - National TAB

Project Issue File Details



C2C47CF5_365D_4534_B9..
10/03/2023



41F78B92_8652_48E4_81..
10/03/2023



10-02-23 ARBY'S 2010 - PURCELL, OK

Project Issue Information

Issue Name : EF-2 Back Draft Damper Obstruction
Description : EF-2 at 50% due to back draft damper obstruction. Fan housing restriction on damper opening.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Originated Date : 10/03/2023 - Darius Payne - National TAB

Project Issue File Details

- 1. [Open](#) IMG_1611.mp4
10/03/2023



0F4F53D5_60EC_4E10_B3..
10/03/2023