

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: PUNCHLIST
Function: Test, Adjust, & Balance
Date: 12/22/2025
Completed By: National TAB

PROJECT

12-22-25 CHIPOTLE # 5650 Cumberland, MD

218 WILLIAMS ST

CUMBERLAND, MD 21502

Client

Chipotle Mexican Grill
610 Newport Center Drive, Suite 1100

Newport Beach, CA 92660

National TAB

Project: 12-22-25 CHIPOTLE # 5650 Cumberland, MD

Table Of Contents

Section	Page #
Remarks	3

Issue List

- EF-2 Backdraft Damper
- HD1: KVS Shut Down Due to Duct Repairs
- RTU1 & RTU2: Filters Dirty



12-22-25 CHIPOTLE # 5650 Cumberland, MD

Project Issue Information

Issue Name : EF-2 Backdraft Damper
Description : No backdraft damper installed to unit.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 12/22/2025 - John Barresi - National TAB



12-22-25 CHIPOTLE # 5650 Cumberland, MD

Project Issue Information

Issue Name : HD1: KVS Shut Down Due to Duct Repairs
Description : Due active welding to fix leaks in exhaust ductwork, KVS system was powered down and partially dismantled. Schedule return after KVS has been reassembled and passed leak test.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Closed
Priority : Urgent **Asset Tag :**
Originated Date : 11/05/2025 - Ryan Smith - National TAB



12-22-25 CHIPOTLE # 5650 Cumberland, MD

Project Issue Information

Issue Name : RTU1 & RTU2: Filters Dirty
Description : Filters in both RTUs are dirty. Replace before return TAB.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Closed
Priority : Low **Asset Tag :**
Originated Date : 11/05/2025 - Ryan Smith - National TAB