



Comfort. Under control.

08-08 PENN STATION - SPRINGFIELD, OH

Project Issue Information

Issue Name : Diffuser missing

Description : One air duct is missing a diffuser in the kitchen. (diffuser 1-8)

Created By : National TAB

Assigned To : National TAB - Joe Hertenstein

Status : Open

Originated Date : 08/09/2022 - Jack Bain - National TAB

Project Issue File Details



FuseIT5bcc12898c5949e6a28f32
29a6862c18.jpeg



MISSING_DIFFUSER.jpg



Comfort. Under control.

08-08 PENN STATION - SPRINGFIELD, OH

Project Issue Information

Issue Name : Exhaust fan for bathroom is not connected

Description : Connection is not made for bathroom exhaust fan. Connecting pieces do not fit.

Created By : National TAB

Assigned To : National TAB - Joe Hertenstein

Status : Open

Originated Date : 08/09/2022 - Jack Bain - National TAB

Project Issue File Details



MISSING_CONNECTION.jpg



FuseIT0307ee17c3c94a9c885d1e
c75f79cb1a.jpeg



Comfort. Under control.

08-08 PENN STATION - SPRINGFIELD, OH

Project Issue Information

Issue Name : LIGHT CONTROLS DAISY CHAINED TOGETHER
Description : GRIDDLE LIGHT CONTROLS ARE CONTROLLED BY FRYER CONTROLS (B2 DE-ENERGIZED ERROR)
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Originated Date : 08/09/2022 - Jack Bain - National TAB

Project Issue File Details



B2_PIC.jpg

Project Issue Response Details

- **08/10/2022 National TAB - Joe Hertenstein**
 - VERIFY IF B2 & W2 ENERGIZE (USING VOLT METER) WITH LIGHT ON / OFF. IF NOT, POWER B2 FROM H1 & W2 FROM N1. THEN POWER GRIDDLE LIGHTS FROM B2 & W2 & B1 & W1 TO GO TO FRYER HOOD. TO BE DONE BY ELECTRICIAN



Comfort. Under control.

08-08 PENN STATION - SPRINGFIELD, OH

Project Issue Information

Issue Name : Outside air dampers

Description : On both units the outside air dampers are wide open or are missing a piece. Also unsure how the damper is controlled if everything is correctly installed.


Created By : National TAB

Assigned To : National TAB - Joe Hertenstein

Status : Open

Originated Date : 08/09/2022 - Jack Bain - National TAB

Project Issue File Details



Fuse1Tbd03fa608458470a82a756
28a7781dd7.jpeg

Project Issue Response Details

- **08/09/2022** **National TAB - Joe Hertenstein**
 - TO BE ABLE TO BALANCE TOTAL AIRFLOW, & TRY TO SET OUTSIDE AIR, TEMPORARILY CLOSE OFF WITH CARDBOARD & TAPE & DOCUMENT. CONTACT GC/MC TO GET PERMANENT SOLUITION.