

Report By:

**National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246**

NATIONAL TAB

Comfort. Under control.

**Report: DEFICIENCY REPORT
Function: Test, Adjust, & Balance
Date: 11/14/2022**

**PROJECT
11-14 CHICK-FIL-A #02053 - WAYCROSS, GA
(WAYCROSS FSU) REINVEST**

2256 MEMORIAL DRIVE

WAYCROSS, GA

Client

CHICK-FIL-A
5200 BUFFINGTON ROAD
ATLANTA, GA 30349-2998

National TAB

Project: 11-14 CHICK-FIL-A #02053 - WAYCROSS, GA (WAYCROSS FSU) REINVEST

Table Of Contents

Section	Page #
Issue Data	3



Comfort. Under control.

11-14 CHICK-FIL-A #02053 - WAYCROSS, GA (WAYCROSS FSU) REINVEST

Project Issue Information

Issue Name : Hood 2 Side Bracket Not Installed

Description : The side bracket is not installed on hood 2.


Created By : National TAB

Assigned To : National TAB - Stephen Tassinaro

Status : Open

Originated Date : 11/14/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseITe739b2d4a8c4491...



Comfort. Under control.

11-14 CHICK-FIL-A #02053 - WAYCROSS, GA (WAYCROSS FSU) REINVEST

Project Issue Information

Issue Name : Hoods 2 & 3 Not Secured At Pre Punched Locations

Description : Hood 2 does not have screws installed in all pre punched holes on the hood, due to this it is not sitting flush with the wall. Hood 3 does not have any pre punched holes, however, it is also not flush with the wall. Installing screws may close the gap. Any gaps left unresolved will collect grease over time.


Created By : National TAB

Assigned To : National TAB - Stephen Tassinaro


Status : Open

Originated Date : 11/14/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseIT7954968d164b4df...



FuseIT1591dad7ab684f3...




Comfort. Under control.

11-14 CHICK-FIL-A #02053 - WAYCROSS, GA (WAYCROSS FSU) REINVEST

Project Issue Information

Issue Name : New RTU #1 No Belt Tensioner
Description : There is no belt tensioner installed on RTU #1.
Created By : National TAB **Assigned To :** National TAB - Stephen Tassinaro
Status : Open
Originated Date : 11/14/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseIT8da9d0fec90411...




Comfort. Under control.

11-14 CHICK-FIL-A #02053 - WAYCROSS, GA (WAYCROSS FSU) REINVEST

Project Issue Information

Issue Name : New RTU #5 GFI Not Functional
Description : GFI inside RTU #5 is not functional.
Created By : National TAB **Assigned To :** National TAB - Stephen Tassinaro
Status : Open
Originated Date : 11/14/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseIT9e65feddda8d471...



Comfort. Under control.

11-14 CHICK-FIL-A #02053 - WAYCROSS, GA (WAYCROSS FSU) REINVEST

Project Issue Information

Issue Name : New RTUs Missing Caulking

Description : New RTUs #1 and #5 do not have caulking installed at the corners of the OA hood.


Created By : National TAB

Assigned To : National TAB - Stephen Tassinaro


Status : Open

Originated Date : 11/14/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseIT4e3c652bc99d46c...



FuseIT8e9c36865e72469...



Comfort. Under control.

11-14 CHICK-FIL-A #02053 - WAYCROSS, GA (WAYCROSS FSU) REINVEST

Project Issue Information

Issue Name : Parts In Grease Trough

Description : See picture for the parts found in the Hood 1 grease trough.


Created By : National TAB

Assigned To : National TAB - Stephen Tassinaro

Status : Open

Originated Date : 11/14/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuselT2a91f1fa2572454...

