

# Test and Balance Punch List - Mar 25, 2024

Prepared by Michael McDonnell

Mar 25, 2024

## Description

2 tasks in this report.

## Contents

#593 Grease Cleanout Doors Sized Incorrectly .....	2
#563 RTU SENSOR LABELS: Improper Label .....	4

**L05068\_Spring Station FSU (KY)**

962 Breckenridge Lane, Louisville, Kentucky

L1020005068

**#593 Grease Cleanout Doors Sized Incorrectly.**

**Status**

Open

**Type**

Planned Work

**List**

TAB Punch List

**Description**

Cleanout doors do not meet size specifications listed in cleanout door schedule on M-250.

**Assignees**

doug@thorndaleconstruction.com

**Watchers**

doug@thorndaleconstruction.com

**Created**


Mar 20, 2024 1:27 PM  
mmcdonnell@nationaltab.com

**Last Updated**

Mar 20, 2024 1:31 PM

**Sheet**

M-250



**Photos**

**L05068\_Spring Station FSU (KY)**

962 Breckenridge Lane, Louisville, Kentucky

L1020005068



IMG\_2813

**Michael McDonnell**

Mar 20, 2024 1:30 PM



IMG\_2826

**Michael McDonnell**

Mar 20, 2024 1:30 PM



IMG\_2814

**Michael McDonnell**

Mar 20, 2024 1:30 PM

## #563 RTU SENSOR LABELS: Improper Label

### Status

Open

### Type

Issue

### Location

Site

### List

TAB Punch List

### Description

See M-501, Detail 1, Note 4:  
1/4" High white  
Lettering on black  
background. Label on wall  
ADJACENT TO DEVICE.  
Sensors improperly  
Labeled.

### Photos

### Assignees

doug@thorndaleconstruction.com

### Watchers

doug@thorndaleconstruction.com

### Created


Mar 18, 2024 2:05 PM  
mmcdonnell@nationaltab.com

### Last Updated

Mar 18, 2024 3:45 PM

### Sheet

M-501



**L05068\_Spring Station FSU (KY)**

962 Breckenridge Lane, Louisville, Kentucky

L1020005068



20240318\_161157\_photo

**Michael McDonnell**

Mar 18, 2024 3:12 PM