



Comfort. Under control.

## 08-15 FIVE GUYS - SAVANNAH, GA

### Project Issue Information

**Issue Name :** EF2

**Description :** EF2 RR FAN IS NOT RUNNING MOTOR IS SEIZED, UNABLE TO BALANCE FAN.

**Created By :** National TAB

**Assigned To :** National TAB - Dale Wheeler

**Status :** Open

**Originated Date :** 08/18/2022 - Dale Wheeler - National TAB

#### Project Issue File Details



SAV4.JPG



Comfort. Under control.

## 08-15 FIVE GUYS - SAVANNAH, GA

### Project Issue Information

**Issue Name :** RTU-E4 ECON

**Description :** ECON IS NOT FUNCTIONING CORRECTLY. OUTSIDE AIR HAD TO BE SET MANUALLY

**Created By :** National TAB

**Assigned To :** National TAB - Dale Wheeler

**Status :** Open

**Originated Date :** 08/18/2022 - Dale Wheeler - National TAB

#### Project Issue File Details



SAV3.jpg



Comfort. Under control.

## 08-15 FIVE GUYS - SAVANNAH, GA

### Project Issue Information

**Issue Name :** SPIRAL DINING ROOM DUCT INSTALLED

**Description :** SPIRAL DINING ROOM DUCT INSTALLED IS CAPPED OFF AND DOES NOT CONNECT TO ANY RTU. FOUR WAY DIFFUSERS WERE INSTALLED IN THE DROP CEILING. THIS IS DIFFERENT THEN WHAT IS SHOWN ON THE GRD.

**Created By :** National TAB

**Assigned To :** National TAB - Wendy Biggs

**Status :** Open

**Originated Date :** 08/18/2022 - Dale Wheeler - National TAB

#### Project Issue File Details



SAV2.JPG



SAV1\_.jpg