



Comfort. Under control.

07-11 CULVERS - ELLISVILLE, MO

Project Issue Information

Issue Name : RTU2 diffusers for dry goods have no dampers
Description : Diffusers for dry goods do not have dampers. The 200 cfm diffuser is high and the 600 cfm diffuser is very low due to excess flex and ceiling restrictions. Since it is in an open area, I do not foresee it causing comfort issues.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Pending
Originated Date : 07/13/2022 - Jacob Davidson - National TAB

Project Issue File Details



FuseIT81eab8d5c64a45b1a32350aa71778eb3.jpeg



FuseIT02554b2b7dfb48dbbccfae17e57cdad.jpeg



FuseIT8b5a4f5c90ce47538d35099b26af319d.jpeg

Project Issue Response Details

- 07/13/2022 National TAB - Jacob Davidson
 - Current airflow for each is 260/200 and 344/600. Pic is another angle looking for damper



FuseIT3b45930d299243e1924652ecb385abb5.jpeg

