

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: PUNCHLIST**  
**Function: Test, Adjust, & Balance**  
**Date: 03/10/2026**  
**Completed By: National TAB**

**PROJECT**  
**03-09-26 QT #0588 OMAHA, NE**

4212 S 84TH STR

OMAHA, NE

**Client**

QUIKTRIP  
4705 SOUTH 129TH EAST AVENUE  
TULSA, OK 74134

# National TAB

Project: 03-09-26 QT #0588 OMAHA, NE

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- EF-1: Damage
- EF-2: Air Leakage
- RT-1: Coil
- RT-2: Condenser Coil
- RT-2: Evaporator Coil



03-09-26 QT #0588 OMAHA, NE

Project Issue Information

**Issue Name :** EF-1: Damage  
**Description :** EF-1 was found off upon arrival. Drive belt is cracked and missing chunks out of it. The cover is also heavily damaged and being held on with zip ties. Recommend replacing drive belt and cover. Unit left turned off.  
**Created By :** National TAB      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Urgent      **Asset Tag :** EF1  
**Originated Date :** 03/10/2026 - Kalen Kemp - National TAB

Project Issue File Details



03/10/2026



03/10/2026



03/10/2026



03-09-26 QT #0588 OMAHA, NE

**Project Issue Information**

**Issue Name :** EF-2: Air Leakage  
**Description :** There is air leakage at the base of EF2. The inlet of the fan slightly overhangs the curb cap. This is affecting fan performance and efficiency. Recommend reworking curb or installing new curb cap to properly seal fan base.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** High                                      **Asset Tag :** EF2  
**Originated Date :** 03/10/2026 - Kalen Kemp - National TAB




03-09-26 QT #0588 OMAHA, NE


**Project Issue Information**

**Issue Name :** RT-1: Coil  
**Description :** The evaporator coil for RT-1 has minor damage.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Low                                      **Asset Tag :** RT-1  
**Originated Date :** 03/10/2026 - Kalen Kemp - National TAB

Project Issue File Details



03/10/2026



03/10/2026



03-09-26 QT #0588 OMAHA, NE

**Project Issue Information**

**Issue Name :** RT-2: Condenser Coil  
**Description :** The condenser coil for RT-2 is damaged. Recommend service.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 03/11/2026 - Kalen Kemp - National TAB

Project Issue File Details



03/11/2026



03-09-26 QT #0588 OMAHA, NE

**Project Issue Information**

**Issue Name :** RT-2: Evaporator Coil  
**Description :** The evaporator coil is dirty on the filter side. There is also some damage on the fan side of this coil. This is affecting unit performance and efficiency. The condenser coil is also damaged. Recommend service.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :** RT-2  
**Originated Date :** 03/10/2026 - Kalen Kemp - National TAB

Project Issue File Details



03/10/2026



03/10/2026



03/10/2026