

**Report By:**

National TAB  
105 Stone Village Drive  
Fort Mill, SC 29708



**Report: Deficiency Report**  
**Function: Test, Adjust, & Balance**  
**Date: 10/24/2025**  
**Completed By: National TAB**

**PROJECT**  
**10-20-25 QT #1141 SIMPSONVILLE, SC**

3005 GRANDVIEW DR

SIMPSONVILLE, SC

**Client**

QUIKTRIP  
4705 SOUTH 129TH EAST AVENUE  
TULSA, OK 74134

## Issue List

- EF-1 not running
- RTU 3 no deflection blades



**10-20-25 QT #1141 SIMPSONVILLE, SC**

**Project Issue Information**

**Issue Name :** EF-1 not running  
**Description :** EF-1 has power and the motor works. The electricians and I trouble-shot the problem and believe it is the speed controller that is not working.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** High                                      **Asset Tag :** EF1  
**Originated Date :** 10/24/2025 - Christian Moller - National TAB

Project Issue File Details



10/24/2025



10-20-25 QT #1141 SIMPSONVILLE, SC

**Project Issue Information**

**Issue Name :** RTU 3 no deflection blades  
**Description :** The tradesman that orders the new cookline diffusers for RTU 3 were not ordered with the deflection blades. If there are drafting issues we will not be able to mitigate them without the blades.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** High                                      **Asset Tag :** RT-3  
**Originated Date :** 10/24/2025 - Christian Moller - National TAB

Project Issue File Details



10/24/2025



10/24/2025