



04-07-25 FREDDY'S HCI - COUNCIL BLUFFS, IA (1305) - RENEW


Project Issue Information

Issue Name : RTU 1, kitchen inducer motor
Description : RTU 1 upon arrival heat would not come on because inducer motor has broken and is hanging a little and not allowing it to spin properly. I pushed it in and resecured to get it to start. Whole time I was here after doing so it would come on and work with a call for heat. Alerted manager about issue to get it fixed before it gets too cold.
Created By : National TAB **Assigned To :** National TAB - Kyle Henry
Status : Open
Priority : **Asset Tag :**
Originated Date : 04/14/2025 - Kyle Henry - National TAB

Project Issue File Details



04/14/2025



04/14/2025