



ENSURE NEAT AND CLEAN INSTALLATION OF ALL EXPOSED DUCTWORK AND AIR DEVICES. AT THE TERMINATION OF WORK, CLEAN ALL EXPOSED DUCTWORK AND AIR DEVICES. EXPOSED DUCTS AND AIR DEVICES SHALL BE FREE OF DIRT, DEBRIS, STICKERS, WRITING, SCRATCHES, OR OTHER FOREIGN OBJECTS OR CONTAMINANTS.

INSTALL SUPPLY AND TRANSFER DUCTS ABOVE BEER CAVE. CAP AS CLOSE TO INDICATED AIR DEVICE LOCATIONS AS POSSIBLE FOR FUTURE CONNECTION. DO NOT INSTALL AIR DEVICES IN BEER CAVE AND RETAIL WALL IF SITE WILL NOT RECEIVE ALCOHOL. LEARNING VERIFY WITH WAIVER IF BEER CAVE SHOULD BE CONVERTED TO ROOM TEMPERATURE SPACE OR REMAIN REFRIGERATED

1 HVAC FLOOR PLAN  
1/4" = 1'-0"