

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Punch list 4/30
Function: Test, Adjust, & Balance
Date: 04/30/2025
Completed By: National TAB

PROJECT
Stone Creek (Greenwood, IN)

1464 W Stones Crossing Rd

Greenwood, IN 46143

Client

C&T DESIGN
4025 PORT UNION RD.
FAIRFIELD, OH 45014

National TAB

Project: Stone Creek (Greenwood, IN)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- Damper missing on S-2-1
- Diffusers S-4-2 and S-4-6



Stone Creek (Greenwood, IN)

Project Issue Information

Issue Name : Damper missing on S-2-1
Description : Airflow on said diffuser is too low to complete balancing. Possibly partially shut
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 04/30/2025 - Aaron Cosby - National TAB



Stone Creek (Greenwood, IN)

Project Issue Information

Issue Name : Diffusers S-4-2 and S-4-6
Description : 2 non square diffusers closet to the vestibule are missing
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 04/30/2025 - Aaron Cosby - National TAB