

# ARBY'S SULLIVAN MO RTU PICTURES

---

Thursday, September 1, 2022

9 Issues Identified



**GENERAL**

Assigned To RTU1  
Condenser coil clean




**GENERAL**

Assigned To RTU1  
Unit filters



**ISSUE**

Assigned To RTU1  
Slight dirt buildup between fins



**GENERAL**

Assigned To RTU1  
Evaporator coil



**ISSUE**

Assigned To RTU1

Dirt buildup on fan wheel



**ISSUE**

Assigned To RTU2

Slight buildup of dirt on condenser coil



**GENERAL**

Assigned To RTU2

Unit filters



**ISSUE**

Assigned To RTU2

Very slight buildup of dirt on evaporator coil, no visible dirt between fins when spot checked.



## **ISSUE**

Assigned To RTU2

Heavy dirt buildup on fan wheel