

PlanGrid Task Report - Nov 1, 2024

Prepared by Dale Wheeler

Nov 1, 2024

Description

2 tasks in this report.

Contents

#9 [REFG 505] [NEW] WIC door sweep vs threshold.....	2
#7 [UNIT 517] [NEW] Condensate piping construction.....	3

#9 [REFG 505] [NEW] WIC door sweep vs threshold.

Status Open	Start Date Oct 31, 2024
Type Planned Work	Created Nov 1, 2024 12:13 PM dale@nationaltab.com
Description WIC door sweep needs to be adjusted.	Last Updated Nov 1, 2024 12:18 PM

Photos



IMG_6051
Dale Wheeler
Nov 1, 2024 12:13 PM

#7 [UNIT 517] [NEW] Condensate piping construction.

Status

Open

Start Date

Oct 31, 2024

Type

Planned Work

Created

Nov 1, 2024 12:12 PM
dale@nationaltab.com

Description

AC1, AC2, AC3 P-traps are missing one union. Unions should be installed on both sides of p-trap.

Last Updated

Nov 1, 2024 12:21 PM

Photos

IMG_6015

Dale Wheeler

Nov 1, 2024 12:12 PM