



Comfort. Under control.

08-29 ARBY'S #5451 - OKMULGEE, OK

Project Issue Information

Issue Name : EF-1 IS DIRTY AND NEEDS TO BE CLEANED

Description : .

Created By : National TAB

Assigned To : National TAB - Michael McDonnell

Status : Open

Originated Date : 08/30/2022 - Will Turnbough - National TAB



Comfort. Under control.

08-29 ARBY'S #5451 - OKMULGEE, OK

Project Issue Information

Issue Name : MUA-1 IS NOT OPERATIONAL

Description : RECOMMENDED REPLACEMENT WITH A NEW MUA AND THAT A PSP BE ADDED IN FRONT OF THE HOOD FOR IMPROVED PERFORMANCE.

Created By : National TAB

Assigned To : National TAB - Michael McDonnell

Status : Open

Originated Date : 08/30/2022 - Will Turnbough - National TAB



Comfort. Under control.

08-29 ARBY'S #5451 - OKMULGEE, OK

Project Issue Information

Issue Name : RTU-1 BELT IS LOOSE

Description : BELT IS LOOSE AND COULD NOT BE TIGHTENED DUE TO A RUSTED BOLT. RECOMMEND PROPERLY TIGHTENING.

Created By : National TAB

Assigned To : National TAB - Michael McDonnell

Status : Open

Originated Date : 08/30/2022 - Will Turnbough - National TAB



Comfort. Under control.

08-29 ARBY'S #5451 - OKMULGEE, OK

Project Issue Information

Issue Name : RTU-2 CONDENSATE DRAIN IS BROKEN

Description : .

Created By : National TAB

Assigned To : National TAB - Michael McDonnell

Status : Open

Originated Date : 08/30/2022 - Will Turnbough - National TAB



Comfort. Under control.

08-29 ARBY'S #5451 - OKMULGEE, OK

Project Issue Information

Issue Name : RTU-2 DINING - HUMIDITY SENSOR IS NOT INSTALLED/WIRED

Description : .

Created By : National TAB

Assigned To : National TAB - Michael McDonnell

Status : Open

Originated Date : 08/30/2022 - Will Turnbough - National TAB

