



Comfort. Under control.

07-25 CULVERS - APOPKA, FL

Project Issue Information

Issue Name : Can't read all of PRV3 motor data
Description : Sticker to the motor is blocked off by fan housing can't read all of data
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Originated Date : 07/25/2022 - Ian Fuller - National TAB

Project Issue Response Details

- 07/25/2022 National TAB - Ian Fuller



FuseIT20d5ff68ac6c4a0e9ed
2a3352c01cb76.jpeg



Comfort. Under control.

07-25 CULVERS - APOPKA, FL

Project Issue Information

Issue Name : Can't lean back hood exhaust fans

Description : Bolt used to keep fan from leaning back does not have enough room to be removed. Therefore the fans can't lean back.


Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 07/25/2022 - Ian Fuller - National TAB

Project Issue File Details



FuseIT6ba2d844e852461fba91e7
ad5a58b979.jpeg



FuseITf91c36093b14476fae9959
48125c8618.jpeg

