

PlanGrid Task Report - Oct 25, 2024

Prepared by Will T

Oct 25, 2024

Description

1 task in this report.

#604 [UNIT 153] Equipment Fresh Air Tempering.

Status

Pending

Created

Dec 5, 2023 3:20 PM
will@nationaltab.com

Type

Planned Work

Last Updated

Oct 25, 2024 4:24 PM

Description

FAT parameters set to standard CFA parameters per the MC, but units do not seem to be operating properly. They appear to be switching between heating and cooling frequently.

Comments

I did not see a comment on this

Will T Jun 27, 2024

The mechanical contractor unhooked the sensors as they could not get them to operate properly. Trane/ Engineer of record need to review.

Will T Oct 25, 2024
