

Report By:

National TAB
105 Stone Village Drive
Fort Mill, SC 29708



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 09/15/2025
Completed By: National TAB

PROJECT

09-08-25 WHATABURGER #1595
KERNERSVILLE, NC

1152 Solomon Dr

KERNERSVILLE, NC 27284

Client

Whataburger Restaurants
300 Concord Plaza Dr
San Antonio, TX 78216

Issue List

- EF-1 MOTOR NOT WORKING



09-08-25 WHATABURGER #1595 KERNERSVILLE, NC


Project Issue Information

Issue Name : EF-1 MOTOR NOT WORKING
Description : EF-1's motor is not working. Electrical double checked that the fan and speed controller were all getting power, yet the fan was still not running. Motor is shot and needs a new one.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Urgent **Asset Tag :** EF1
Originated Date : 09/15/2025 - Chistian Moller - National TAB

Project Issue File Details



09/15/2025



09/15/2025