



REMOTE SENSORS  
RTU-2 56" A.F.F.  
HUMIDITY AND  
TEMPERATURE

STACK THERMOSTATS VERTICALLY,  
COORDINATE LOCATION W/  
POS SYSTEM COMPONENTS

VERIFY DRYER  
VENTING  
REQUIREMENTS  
WINDOW

