

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: PUNCHLIST**  
**Function: Test, Adjust, & Balance**  
**Date: 11/13/2025**  
**Completed By: National TAB**

**PROJECT**  
**Marshalltown (Kansas City, KS)**

9800 Leavenworth Rd

Kansas City, KS 66109

**Client**

Temp-Con, Inc.  
15670 S Keller St  
Olathe, KS 66062

# National TAB

Project: Marshalltown (Kansas City, KS)

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- RTU-1: Unit not Running/Thermostat not functional



## Marshalltown (Kansas City, KS)

### Project Issue Information


**Issue Name :** RTU-1: Unit not Running/Thermostat not functional  
**Description :** RTU-1 is not running. Not receiving correct signal from thermostat. Thermostat not reading space conditions properly. Unable to adjust controls. Recommend checking the wiring/connection at thermostat and RTU.

**Created By :** National TAB                      **Assigned To :** National TAB - Kalen Kemp  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :** RTU1  
**Originated Date :** 11/13/2025 - Kalen Kemp - National TAB


#### Project Issue File Details



11/13/2025



11/13/2025



11/13/2025