

Report By:

National TAB
105 Stone Village Drive
Fort Mill, SC 29708



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 01/13/2026
Completed By: National TAB

PROJECT
01-12-26 QT #0823 LITHONIA, GA

2841 TURNER HILL RD

LITHONIA, GA

Client

QUIKTRIP
4705 SOUTH 129TH EAST AVENUE
TULSA, OK 74134

Issue List

- Dirty final filters
- Final diffusers not installed



01-12-26 QT #0823 LITHONIA, GA

Project Issue Information

Issue Name : Dirty final filters
Description : All RTU's have dirty final filters. These should be replaced soon.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :**
Originated Date : 01/13/2026 - Christian Moller - National TAB

Project Issue File Details



01/13/2026



01/13/2026



01/13/2026



01-12-26 QT #0823 LITHONIA, GA


Project Issue Information

Issue Name : Final diffusers not installed
Description : The final diffusers for the combi oven as well as the cook line diffusers have not been installed. The GC does not know when they will be installed.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 01/13/2026 - Christian Moller - National TAB

Project Issue File Details



01/13/2026



01/13/2026