

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: CW 3300 Allstate Issues
Function: Test, Adjust, & Balance
Date: 06/12/2025
Completed By: National TAB

PROJECT
CW 3300 - Allstate (Dallas, TX)

3300 Olympus Blvd

Dallas, TX 75019

Client

Billingsley

National TAB

Project: CW 3300 - Allstate (Dallas, TX)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- FCU-4-2.6 Missing Diffuser
- FCU-4-3.2 Return Blocked
- FCU4-1.2 Missing Diffuser
- FCU4-4.2 Missing Diffuser
- FCU4-4.4 Missing Diffuser



CW 3300 - Allstate (Dallas, TX)

Project Issue Information

Issue Name : FCU-4-2.6 Missing Diffuser
Description : Missing diffuser #3.
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 06/11/2025 - Bayley Morvant - National TAB

Project Issue File Details



06/11/2025



CW 3300 - Allstate (Dallas, TX)

Project Issue Information

Issue Name : FCU-4-3.2 Return Blocked
Description : Unit return is either blocked by blue plastic or has closed damper above closed off ceiling in XL Conference 408. This is above ceiling tiles that are metal and locked in place. This will require the ceiling company to come out and remove one of these tiles in order to access return.
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 06/11/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 3300 - Allstate (Dallas, TX)


Project Issue Information

Issue Name : FCU4-1.2 Missing Diffuser
Description : Unit is missing diffuser #10 above table.
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 06/12/2025 - Bayley Morvant - National TAB

Project Issue File Details



06/12/2025



06/12/2025



CW 3300 - Allstate (Dallas, TX)

Project Issue Information

Issue Name : FCU4-4.2 Missing Diffuser
Description : Missing diffuser #5.
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 06/11/2025 - Bayley Morvant - National TAB



CW 3300 - Allstate (Dallas, TX)

Project Issue Information

Issue Name : FCU4-4.4 Missing Diffuser
Description : Unit is missing diffuser #1.
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 06/12/2025 - Bayley Morvant - National TAB

Project Issue File Details

