

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Issue Data
Function: Test, Adjust, & Balance
Date: 12/04/2025
Completed By: National TAB

PROJECT
CW 8950 - Mr Cooper (Coppell, TX)

8950 Cypress Waters Blvd.

Coppell, TX 75019

Client

Pacific Builders
7950 Legacy Dr.
Suite 150
Plano, TX 75024

National TAB

Project: CW 8950 - Mr Cooper (Coppell, TX)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- FPB-E3.20 Control Issue
- FPB-E3.21 Control Issue
- FPB3.3-B Primary Air Damper Not Functional
- FPBE3-10 Fan Not Operational
- FPBE3-11 Fan Not Operational
- FPBE3.1 Showing "NR" on Controls
- FPBE3.14 Fan not operational
- FPBE3.2 Showing "NR" on Controls
- FPBE3.23 Showing "NR" on Controls
- FPBE3.4 Showing "NR" on Controls
- FPBE3.6 Showing "NR" on Controls



CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPB-E3.20 Control Issue
Description : FPB-E3.20(FPB3-46 on controls graphics) does not pull up the right box when opened on control graphics. Box is labeled as FPB3-46 on control graphics, however it opens box FPB3-47. The only way to access the correct box is to go through the RTU matrix page.


Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert

Status : Open

Priority : InfoOnly **Asset Tag :**

Originated Date : 12/02/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPB-E3.21 Control Issue
Description : FPB-E3.21(FPB3-45 on controls graphics) does not pull up the right box when opened on control graphics. Box is labeled as FPB3-45 on control graphics, however it opens box FPB2-18. The only way to access the correct box is to go through the RTU matrix page.
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : InfoOnly **Asset Tag :**
Originated Date : 12/02/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPB3.3-B Primary Air Damper Not Functional
Description : Unit motorized primary air damper is not functioning correctly. Damper stays in closed position even though box is at 0 cfm and is calling for design of 500 cfm. Unable to calibrate and balance box until this is addressed.
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 01/13/2026 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3-10 Fan Not Operational
Description : Fan not operational during time of testing. Unit is an existing box. (controls label is FPB3-38)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 01/13/2026 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3-11 Fan Not Operational
Description : FPB3E3-11 fan is not operational. Unit is an existing box. (Controls label is FPB3-51)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 12/09/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3.1 Showing "NR" on Controls
Description : FPBE3.1 is showing "NR" on controls. Unit is not operational. (Box labeled as FPB3-32 on controls)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/04/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3.14 Fan not operational
Description : Fan not operational during time of testing. Unit is existing box. (box labeled as FPB3-48 on controls graphics)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 12/02/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3.2 Showing "NR" on Controls
Description : FPBE3.2 is showing "NR" on controls. Box is not operational. (Box labeled as FPB3-31 on controls)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/04/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3.23 Showing "NR" on Controls
Description : FPBE3.23 is showing "NR" on controls. Unable to control box to calibrate and balance. (Controls name for thie box is FPB3-43)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/03/2025 - Bayley Morvant - National TAB

Project Issue File Details






CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3.4 Showing "NR" on Controls
Description : FPBE3.4 is showing "NR" on controls and is not operational. (Box labeled as FPB3-34 on controls graphics)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/04/2025 - Bayley Morvant - National TAB

Project Issue File Details





CW 8950 - Mr Cooper (Coppell, TX)

Project Issue Information

Issue Name : FPBE3.6 Showing "NR" on Controls
Description : FPBE3.6 is showing "NR" on controls. Box is not operational. (Box labeled as FPB3-30 on controls)
Created By : National TAB **Assigned To :** National TAB - Stephan Gabbert
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/04/2025 - Bayley Morvant - National TAB

Project Issue File Details

