

Issue List

- Diffuser 1-1 (Restroom) diffuser face loose
- Diffuser 1-2 missing damper
- KEF-1: Not running
- KSF-1: Damper not opening



Jersey Mikes (Liberty, MO)

Project Issue Information

Issue Name : Diffuser 1-1 (Restroom) diffuser face loose
Description : Face of diffuser came loose during balancing. Temporarily secured with foil tape
Created By : National TAB **Assigned To :** National TAB - Kalen Kemp
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 07/08/2025 - Will Turnbough - National TAB

Project Issue File Details






Jersey Mikes (Liberty, MO)

Project Issue Information

Issue Name : Diffuser 1-2 missing damper
Description : Airflow for diffuser 1-2 is above design but diffuser 1-3 in the same area is a little below design. Likely won't cause any comfort issues but damper is needed on 1-2 to balance both within design.

Created By : National TAB **Assigned To :** National TAB - Kalen Kemp
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 07/08/2025 - Will Turnbough - National TAB

Project Issue File Details





Jersey Mikes (Liberty, MO)

Project Issue Information

Issue Name : KEF-1: Not running
Description : Fan is not running. No power to disconnect.
Created By : National TAB **Assigned To :** National TAB - Kalen Kemp
Status : Open
Priority : Urgent **Asset Tag :** KEF-1
Originated Date : 07/07/2025 - Kalen Kemp - National TAB

Project Issue File Details



07/07/2025



Jersey Mikes (Liberty, MO)

Project Issue Information

Issue Name : KSF-1: Damper not opening
Description : Fan is running but damper is not opening. Airflow is low.
Created By : National TAB **Assigned To :** National TAB - Kalen Kemp
Status : Open
Priority : Urgent **Asset Tag :** KSF-1
Originated Date : 07/07/2025 - Kalen Kemp - National TAB

Project Issue File Details



07/07/2025