

# TAB PUNCLIST

Prepared by David Annan

Jan 21, 2025

## Description

1 task in this report.

## #237 Broken Condensate lines on the roof

**Status**

Open

**Assignees**

tony.smith@getsterling.com

**Type**

Planned Work

**Watchers**

bob.howell@jll.com  
tony.smith@getsterling.com

**Location**

Roof

**Start Date**

Jan 14, 2025

**List**

GC Punch List

**Due At**

Jan 31, 2025

**Description**

There are some broken Condensate lines on the roof. Recommend that the lines be repaired.

**Created**

Jan 21, 2025 11:02 AM  
david@nationaltab.com

**Last Updated**

Jan 21, 2025 11:05 AM

**Photos**



IMG\_6847  
**David Annan**  
Jan 21, 2025 11:04 AM



IMG\_6885  
**David Annan**  
Jan 21, 2025 11:04 AM