



**08-14-23 FREDDY'S - ROANRIDGE RD (KANSAS CITY, MO) - RENEW**

**CheckList Information**

**Name :** Renew-Certificate of Completion **Status :** Completed  
**Assigned Organization :** National TAB **Asset :**  
**Requesting Organization :** National TAB

**CheckList Item Details**

**ROOFTOP UNITS**

DEBRIS CLEANED FROM MIXED AIR AND BLOWER COMPARTMENT, BLOWER WHEEL, DRIVE ASSEMBLY, COMBUSTION FAN COMPARTMENT AND HEAT EXCHANGER. EACH COMPARTMENT THEN VACUUMED USING A SHOP VAC AND THEN WIPED CLEAN WITH A DAMP CLOTH Yes

Comment



**1.jpeg**



**2(1).jpeg**

MOTOR AIR VENTS HAVE BEEN CLEANED AND SHOP VACUUMED TO ENSURE DEBRIS DOES NOT FALL BACK INTO THE MOTOR CASING Yes

Comment

EVAPORATIVE COIL DEGREASED AND WASHED CLEAN Yes

Comment



1.jpeg



2(1).jpeg



3.jpeg

DRAIN PAN WASHED DOWN AND CLEANED, FREE OF DEBRIS

Yes

Comment

CONDENSATE DRAIN FLUSHED TO ENSURE NO BLOCKAGE - WATER FREELY FLOWS FROM DRAIN PAN THROUGH THE CONDENSATE DRAIN LINE TO THE ROOF DRAIN.

Yes

Comment



1.jpeg



2(1).jpeg


CONDENSER COIL HAIL GAURD REMOVED, COIL DEGREASED AND WASHED FROM REAR OF COIL, ALL EXCESS DEBRIS REMOVED PRIOR TO REINSTALLING THE HAIL GUARD

Yes


Comment



1.jpeg



2(1).jpeg



3.jpeg

CONDENSER FANS CHECKED FOR LOOSE FASTENERS AND UNUSUAL VIBRATION, MOTOR AND FAN WHEELS CLEANED OF DEBRIS AND WIPED DOWN WITH DAMP CLOTH

Comment

EVAPORATIVE COIL FILTERS REPLACED WITH CLEAN FILTERS

Yes

Comment



1.jpeg



2(1).jpeg



3.jpeg

OUTDOOR AIR FILTERS CLEANED AND REINSTALLED IN THE OA AWNING

Yes

Comment



1.jpeg



2(1).jpeg



3.jpeg

MOTOR AND BLOWER WHEEL INSPECTED FOR FAILING/FAILED BEARINGS

Yes

Comment

BELT REPLACED ON DRIVE IF CURRENT CYCLE REQUIRES A NEW BELT

Yes

Comment



1.jpeg



2(1).jpeg



3.jpeg

UNIT TURNED BACK ON AND VALIDATED THE UNIT IN RUNNING CONDITION PRIOR TO LEAVING

Yes

Comment

**EXHAUST FANS**

EXHAUST STACK REMOVED TO ACCESS MOTOR HOUSING (IF STACK INSTALLED ON THE FAN)

Yes

Comment

MOTOR HOUSING WIPED DOWN WITH DRY CLOTH AND DRY SHOP VACUUM USED TO REMOVE ALL EXCESS DEBRIS.

Yes

Comment

MOTOR AIR VENTS HAVE BEEN CLEANED AND SHOP VACUUMED TO ENSURE DEBRIS DOES NOT FALL BACK INTO THE MOTOR CASING

Yes

Comment

COOLING TUBE FROM FAN SHELL TO MOTOR HOUSING INSPECTED AND CLEANED OF ALL DIRT AND DEBRIS

Yes

Comment



1.jpeg



2(1).jpeg



3.jpeg

USE DAMP CLOTH TO WIPE DOWN ALL FINAL SURFACES

Yes

Comment

MOTOR AND FAN WHEELS INSPECTED FOR FAILING/FAILED BEARINGS

Yes

Comment

BELT REPLACED ON DRIVE IF CURRENT CYCLE REQUIRES A NEW BELT

No

Comment

MOTOR LID PUT BACK ON HOUSING AND STACK RE-INSTALLED (IF PRESENT)

Yes

Comment

HINGE KIT AND ELECTRICAL WHIP INSPECTED FOR PROPER INSTALLATION

Yes

Comment

GREASE CUP / GREASE CATCH SYSTEM INSPECTED FOR PROPER INSTALLATION

Yes

Comment

FAN TURNED BACK ON PRIOR TO LEAVING SITE AND ENSURED PROPER OPERATION OF THE FAN AT THE ROOF AND KITCHEN HOOD.

Yes

Comment

**MUA FAN**

BLOWER AND HEATER HOUSING WIPED DOWN WITH DRY CLOTH AND DRY SHOP VACUUM USED TO REMOVE ALL EXCESS DEBRIS. INCLUDES: BLOWER WHEEL, BLOWER HOUSING, DRIVE ASSEMBLY, MOTOR BASE AND MOTOR, ALL INTERNAL WALLS AND CEILINGS, BURNER PROFILE PLATES, BURNER, BURNER ASSEMBLY, & MOTORIZED DAMPER

Yes

Comment



1.jpeg



2(1).jpeg

MOTOR AIR VENTS HAVE BEEN CLEANED AND SHOP VACUUMED TO ENSURE DEBRIS DOES NOT FALL BACK INTO THE MOTOR CASING

Yes

Comment

USE DAMP CLOTH TO WIPE DOWN ALL FINAL SURFACES

Yes

Comment

MOTOR AND FAN WHEELS INSPECTED FOR FAILING/FAILED BEARINGS

Yes

Comment

BELT REPLACED ON DRIVE IF CURRENT CYCLE REQUIRES A NEW BELT

Yes

Comment



1.jpeg

OA MESH FILTERS HAVE BEEN CLEANED AND FREE OF DEBRIS Yes

Comment



Oa.jpeg

UNIT HAS BEEN TURNED BACK ON AND CONFIRMED OPERATIONAL AT THE UNIT AND THE KITCHEN HOOD Yes

Comment

**MUA HEAT SECTION**

GAS HEAT TURNED ON (IF IN SEASON) AND ENSURED FLAME WITH PROPER INTAKE AND DISCHARGE TEMPERATURE SETTINGS Yes

Comment

**MUA COOLING SECTION**

IF UNIT HAS COOLING: DX COIL WAS DEGREASED AND WASHED DOWN

Comment

DRAIN PAN CLEANED OF DEBRIS

Comment

CONDENSATE DRAIN IS INSTALLED AND FLUSHED TO ALLOW ALL WATER TO PROPERLY DRAIN

Comment

CONDENSER COIL(S) CLEANED

Comment

**ADDITIONAL INSPECTIONS**

ALL UNITS INSPECTED FOR CORRECT INSTALLATION, DEFECTS, OR OPERATIONAL ISSUES. IF ANY FOUND A ISSUE WAS CREATED WITH REQUIRED PHOTO'S OR VIDEO.	Yes
--	-----

Comment

BUILDING PRESSURE IS NEUTRAL	Yes
------------------------------	-----

Comment

HOOD CAPTURE IS 100% DURING NORMAL COOKING PERIODS	Yes
--	-----

Comment

THERMOSTATS ARE PROPERLY PROGRAMMED	Yes
-------------------------------------	-----

Comment

**Notes/Comments :**