



Shake Shack (Oak Lawn, IL) - Commissioning

CheckList Information

Name : FIV - (Above Ceiling) Electrical Rough-In **Status :** NotSubmitted
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB

CheckList Item Details

Lighting & Power above ceiling inspection (main power - lighting symbol key attached)

- [Open](#) lighting_symbol_key.PNG

- Drive thru (space 111) inspected and compared to sheet E120.

- [Open](#) drive_thru_lighting.PNG

- BOH kitchen prep (space 112) inspected and compared to sheet E120

- [Open](#) boh_serve_line_lighting.PNG

- BOH kitchen cook and serve lines areas inspected (space 109 & 110) and compared to sheet E120

- [Open](#) cookline_and_serve_line_lighting.PNG

- Office (space 115) inspected and compared to sheet E120

- [Open](#) managers_office.PNG

- Mechanical room (space 116) lighting compared to sheet E120

- [Open](#) mech_room.PNG

- Mens and Womens Restrooms (space 106 and 107) lighting compared to sheet E120

- [Open](#) restrooms.PNG

- Dining room soffit details compared to sheet E120

- [Open](#) soffit_lighting_power.PNG

- Main Dining Room compared to sheet E120

- [Open](#) dining_room.PNG

- Patio Lighting & Power Junctions compared to sheet E120

- [Open](#) epatio.PNG