



## Shake Shack (Oak Lawn, IL) - Commissioning

### CheckList Information

<b>Name :</b>	FIV - (Above Ceiling) Electrical Rough-In	<b>Status :</b>	NotSubmitted
<b>Assigned Organization :</b>	National TAB	<b>Asset :</b>	
<b>Requesting Organization :</b>	National TAB		

### CheckList Item Details

**Lighting & Power above ceiling inspection (main power - lighting symbol key attached)**

- [Open](#) lighting\_symbol\_key.PNG

---

- Drive thru (space 111) inspected and compared to sheet E120.

---

- [Open](#) drive\_thru\_lighting.PNG

---

- BOH kitchen prep (space 112) inspected and compared to sheet E120

---

- [Open](#) boh\_serve\_line\_lighting.PNG

---

- BOH kitchen cook and serve lines areas inspected (space 109 & 110) and compared to sheet E120

---

- [Open](#) cookline\_and\_serve\_line\_lighting.PNG

---

- Office (space 115) inspected and compared to sheet E120

---

- [Open](#) managers\_office.PNG

---

- Mechanical room (space 116) lighting compared to sheet E120

---

- [Open](#) mech\_room.PNG

---

- Mens and Womens Restrooms (space 106 and 107) lighting compared to sheet E120

---

- [Open](#) restrooms.PNG

---

- Dining room soffit details compared to sheet E120

---

- [Open](#) soffit\_lighting\_power.PNG

---

- Main Dining Room compared to sheet E120

- [Open](#) dining\_room.PNG
- [Open](#) e\_euh\_vestibule.PNG

---

- Patio Lighting & Power Junctions compared to sheet E120

---

- [Open](#) epatio.PNG
  - [Open](#) epation\_heater\_above\_celing.PNG
-