


RETURN AIR REMOVED. NO RETURN AIR IN THE FRONT OF HOUSE THAT I COULD SEE




ONE THERMOSTAT POSITIVE AIR IN FRONT OF HOUSE,




MECHANICAL PLAN SCALE: 1/8"=1'-0" NORTH



DUCTLESS VENTS ABOVE BACK OF HOUSE DOOR. DOOR NEEDS TO REMAIN OPEN OTHERWISE SHOWROOM IS POSITIVE AND CREATES LOUD WISTLE AT FRONT DOOR. ALSO, NEGATIVE IN BACK OF HOUSE



VERY LOUD UNIT WITH STRONG AIR FLOW



RETURN AIR REMOVED. NO RETURN AIR IN THE FRONT OF HOUSE THAT I COULD SEE

