

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: test

Function: Test, Adjust, & Balance

Date: 10/24/2023

PROJECT
cache test

Test 123 blvd

Test, TX 11111

Client

Test 123

National TAB

Project: cache test

Table Of Contents

Section	Page #
Balance Schedule Grid	3
Diffuser Supply (GRD)	4



National TAB

Project:cache test

Balance Schedule Grid

balance schedule/

Asset								
Asset Name	SUPPLY DCFM	SUPPLY ACFM	RETURN_DCFM	RETURN_ACFM	OA_DCFM	OA_ACFM	EXH_DCFM	EXH_ACFM
EF2							3200	3200
EF3							500	450
EF4							500	560
EF5							500	500
EF6							467	456
KEF1							800	800
MUA1	4000				40000	4000		
RTU1	3000	3000	2000	1800	800	780		
RTU2	3000	2500	2000	2200	800	890		
RTU3	2000	32090	2000	2000	600	660		



National TAB

Project:cache test

Diffuser Supply (GRD)

test/

Asset									
Asset Name	Location	Type	Size	DESIGN CFM	AK	CFM(1)	CFM(2)	FINAL CFM	% to design
SGRD1									
SGRD2									
SGRD3									
SGRD4									
SGRD5									
SGRD6									
SGRD7									
SGRD8									
SGRD9									
SGRD10									
Total				0		0	0	0	0%