



Comfort. Under control.

08-01 FREDDY'S 316RG - FLORENCE, SC - RENEW 4 (1)

CheckList Information

Name : RENEW - SITE PICTURES (FREDDY W/DOAS) **Status :** NotSubmitted
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB

CheckList Item Details

ROOF TOP BEFORE AND AFTER PICTURES

DOAS 1 O.A. FILTER (BEFORE AND AFTER)



Dirty.jpeg



Clean.jpeg

DOAS 1 FINAL FILTER (BEFORE AND AFTER)



Clean.jpeg




Dirty.jpeg

DOAS 1 CONDENSOR COIL (BEFORE AND AFTER)



Clean.jpeg



Dirty.jpeg

DOAS 1 EVAPORATOR COIL (BEFORE AND AFTER)



Dirty.jpeg



File.jpeg



Clean.jpeg

DOAS 1 - CONDENSATE DRAIN



Complete.jpeg

DOAS 1 CONDENSATE PAN



Complete.jpeg

RTU 1 OA MESH FILTER (BEFORE AND AFTER)




DIRTY.jpeg



Clean.jpeg

RTU1 1 FINAL FILTER (BEFORE AND AFTER)



DIRTY.jpeg



Clean.jpeg

RTU 1 CONDENSOR COIL (BEFORE AND AFTER)



DIRTY.jpeg




DIRTY.jpeg



File.jpeg

RTU 1 EVAPORATOR COIL (BEFORE AND AFTER)



DIRTY.jpeg



Clean.jpeg

RTU 1 CONDENSATE DRAIN



Complete.jpeg

RTU 1 CONDENSATE PAN



Complete.jpeg

EXHAUST FAN BEFORE AND AFTER PICTURES

EXHAUST FAN KEF1 MOTOR HOUSING CLEANED

Yes



Clean.jpeg

EXHAUST FAN KEF1 GREASE CUP PROPERLY
INSTALLED

Yes



Full.jpeg

EXHAUST FAN KEF2 MOTOR HOUSING CLEANED

Yes



FuselT458c46973a484e.jpeg

EXHAUST FAN KEF2 GREASE CUP PROPERLY
INSTALLED

Yes



FuselT703a7517b54144.jpeg

EXHAUST FAN KEF3 MOTOR HOUSING CLEANED

Yes



**FuselT34bac7f1165d4c.j
peg**

EF-1 RESTROOMS FAN HOUSING PICTURE

Yes



**FuselT320c1b47c7ec4b.j
peg**

EF-2 RESTROOMS FAN HOUSING PICTURE

Yes



**FuselTcf58c2b7831643.jp
eg**