

Project Summary:

Overview

Purpose of the visit to Chick-fil-A #2367 in Ocala, FL was to replace pulley on AC#1 to make unit within design air flow tolerance.

Findings

1. AC#1 (Kitchen Unit)
 - a) Pulley was replaced and unit came within design airflow.
 - b) OA is within design air flow tolerance.
2. Rest of AC units
 - a) Found in working condition, left as is