Comfort. Under control.

04-18 EUROPEAN WAX CENTER - SAN DIEGO, CA (DEL MAR) TAB+ IAQ

Project Issue Information

Issue Name : LOW PRIORITY - RTU outside air filter is not installed.

Description : Recommend installing to prevent bugs and debris from entering the unit and ductwork.

Created By : National TAB **Assigned To :** National TAB - Will Turnbough

Status : Open

Originated Date : 04/22/2022 - Will Turnbough - National TAB

Project Issue File Details

20220420_231653764_iOS.jpg