

CheckList List

- Walgreens Survey-Exterior Pics
- Walgreens Survey-Interior Pics



08-12-24 WALGREENS #5460 PONTIAC, IL

CheckList Information

Name : Walgreens Survey-Exterior Pics **Status :** Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/14/2024 - Megan McKelvey - National TAB
Completed Date : 08/14/2024 - Dylan Crisman - National TAB

CheckList Item Details

Take picture of front of building.

Comment:



08/14/2024

Picture of back of building.

Comment:



08/14/2024

Pictures of left & right side of building.

Comment:



08/14/2024



08/14/2024

Picture(s) of overall roof layout.

Comment:



08/14/2024



08/14/2024



08-12-24 WALGREENS #5460 PONTIAC, IL

CheckList Information

Name : Walgreens Survey-Interior Pics **Status :** Completed
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB
Created Date : 08/14/2024 - Megan McKelvey - National TAB
Completed Date : 08/14/2024 - Dylan Crisman - National TAB

CheckList Item Details

Interior retail space.

Comment:



08/14/2024




08/14/2024



08/14/2024

Office area.

Comment:



08/14/2024

Picture of thermostat RTU 1. List manufacturer/model number if available.

Comment:



08/14/2024

Picture of thermostat RTU 2. List manufacturer/model number if available.

Comment:



08/14/2024

Picture of thermostat RTU 3. List manufacturer/model number if available.

Comment:



08/14/2024

Picture of thermostat RTU 4. List manufacturer/model number if available.

Comment:



08/14/2024

Picture of thermostat RTU 5. List manufacturer/model number if available.


Comment:



08/14/2024

Stock room / storage area.

Comment:



08/14/2024

Employee breakroom (if applicable).

Comment:



08/14/2024

Above ceiling RTU 1 supply & return drop.

Comment:

NA

Above ceiling RTU 2 supply & return drop.

Comment:

NA

Above ceiling RTU 3 supply & return drop.

Comment:

NA

Above ceiling RTU 4 supply & return drop.

Comment:

NA

Above ceiling RTU 5 supply & return drop.

Comment:

NA

Ceiling of vestibule (if applicable).

Comment:

NA

Fire panel (if exists). Take picture of front of panel. If able to open panel door easily, take a picture of inside panel. List manufacturer/model number of panel if available.

Comment:

Model 5207



08/14/2024



08/14/2024



08/14/2024