



Comfort. Under control.

06-13 BLUE SUSHI - NASHVILLE, TN

Project Issue Information

Issue Name : Building pressure is negative.

Description : Building pressure was measured as -0.03" wc at the front door of Blue Sushi. The pressure will likely be more negative once the cleanout door is installed and air is exhausted out of the building.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 06/05/2022 - Will Turnbough - National TAB





Comfort. Under control.

06-13 BLUE SUSHI - NASHVILLE, TN

Project Issue Information

Issue Name : Missing and loose cleanout door

Description : There is one missing cleanout door located in the discharge duct run of the pcu. There is also a loose cleanout door see pictures for locations

Created By : National TAB **Assigned To :** National TAB - Will Turnbough

Status : Open

Originated Date : 06/05/2022 - Tyler Youells - National TAB


Project Issue File Details



MicrosoftTeams_image_5_.png

Project Issue Response Details

- **06/05/2022** **National TAB - Will Turnbough**
 - Loose cleanout door and access panel locations to access both doors.



MicrosoftTeams_image_6_.png



loose_cleanout_door.png







Comfort. Under control.

06-13 BLUE SUSHI - NASHVILLE, TN

Project Issue Information

Issue Name : PCU Turning off

Description : -

Created By : National TAB

Assigned To : National TAB - Tyler Youells

Status : Open

Originated Date : 06/05/2022 - Will Turnbough - National TAB

