



Nestle (Mt Sterling, KY)

Project RFI Information

Issue Name :	GMAU 24/25	Organization :	GMAU 24/25
Status :	Open	Assigned To :	National TAB - JOE HERTENSTEIN
Shared To :		Created :	Tyler Youells
Open :	05/18/2021	Description:	Units have dirty return filters located in the packing mezz. Unit 24 was read out and it was determined filters are a big airflow issue. James was notified and he stated he will make a PM to fix. We are holding off on reading out Gmau 25
	- Tyler Youells - National TAB		

Project RFI File Details

1. [Open](#) File.jpg