



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-20-96 / WEST MAINTANCE SHOP	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Mounted on sidewalk above blue door. Fan is not currently running. Switch location is unknown. Maintenance does not know where switch is
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open FuseIT2021-06-17T10274505248c79-2eb1-410a-a7b0-273c4df193e5.jpg 	
Fan total pressure recorded.	
Is Fan interlocked with any other asset? if so, list:	
When is fan used (application) and any specific time?	Heat evac in summer?
Make, Model, and Serial Number:	
Attach picture of asset.	
Fan CFM:	[1]