



## Nestle (Mt Sterling, KY)

### CheckList Information

<b>Name :</b>	EF-20-96 / WEST MAINTANCE SHOP	<b>Status :</b>	NotSubmitted
<b>Assigned Organization :</b>	National TAB	<b>Asset :</b>	
<b>Requesting Organization :</b>	National TAB		

### CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Mounted on sidewalk above blue door. Fan is not currently running. Switch location is unknown. Maintenance does not know where switch is
Attach picture of asset.	Yes
<ul style="list-style-type: none"> <li>• <a href="#">Open</a> FuseIT2021-06-17T10274505248c79-2eb1-410a-a7b0-273c4df193e5.jpg</li> </ul>	
Fan total pressure recorded.	No
Is Fan interlocked with any other asset? if so, list:	NO, BUT LIKELY NEEDS TO BE TIED TO MUA UNIT
When is fan used (application) and any specific time?	Heat evac in summer
Make, Model, and Serial Number:	UNIT DATA NOT ACCESIBLE
Attach picture of asset.	Yes
Fan CFM:	[1] UNABLE TO MEASURE. NEED FAN TO RUN AND TO FIND SWITCH, ALSO REQUIRES A LIFT