



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-1-95 / L4/5 FREEZER MEZZ	Status :	Submitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Unit does not run. Facilities does not know where switch is Unit data: Hartzell 63-36-LJ3 Serial:95C485 Motor: 2 hp 460 Amps NL
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan total pressure recorded.	No
Is Fan interlocked with any other asset? if so, list:	No.
When is fan used (application) and any specific time?	Used for heat evacuation of the oven mezz room