



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-HYDRAULIC ROOM	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	NO VISUAL ISSUES. UNIT ORIGINALLY THOUGHT TO BE PAIRED WITH A SF HOWEVER UPON FURTHER INSPECTION THE SF IS JUST A VENT.
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan total pressure recorded.	Yes
Is Fan interlocked with any other asset? if so, list:	FAN IS STANDALONE, BUT THERE IS A VENT THAT EQUALIZES ROOM PRESSURE.
When is fan used (application) and any specific time?	USED WHEN HYDRAULIC ROOM IS HOT.
Make, Model, and Serial Number:	UNIT DATA: HARTZELL MN:69-12-WF3 9803010 MOTOR: 0.5HP 460V 1A SP:-0.29"
Fan CFM:	