



Nestle (Mt Sterling, KY)

CheckList Information

Name :	MAU-3-96 / WEST MAINTENANCE SHOP	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

MAU

Observe unit to ensure operational & no visual issue. If any comment. Note # of Duct Drops.	Belt is warn out and rotted. Facilities does not know where switch is so cannot test unit.
<ul style="list-style-type: none"> • Open FuseIT2021-06-17T10371573767327-1fd6-4f50-9cb2-b1131847975c.jpg 	
Unit Has Exhaust\Relief Fans & How Many. Note N/A if this does not apply.	Na
Verify outside air damper position & note approximate open amount (visual). Attached Picture	Na
No Relief/Exhaust in Operation @ Time of Testing. Note "N/A" if this system does not have Relief/Exhaust	Na
Fan Total Pressure Recorded	
Fan VFD Speed (HZ)	Na
OA Damper Position (Controls Output) include picture of damper position.	Na
Attach picture of each asset	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Unit Operation	
Heating	Yes
Cooling	No
Wash-Down Validation	N/A
Make, Model, and Serial Number:	Unit data Trane: DFOA118FNBA2ACC11 Serial: A97E36614 460V 5hp 8A
Fan CFM:	0

