



Nestle (Mt Sterling, KY)

CheckList Information

Name : SF 7-96 L6/8 OVEN ROOM **Status :** NotSubmitted
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB

CheckList Item Details

MAU

Observe unit to ensure operational & no visual issue. If any comment. Note # of Duct Drops.	1 drop. Fan was not previously running but is now.
---	--

Unit Has Exhaust\Relief Fans & How Many. Note N/A if this does not apply.	Na
---	----

Verify outside air damper position & note approximate open amount (visual). Attached Picture	Damper open
--	-------------

No Relief/Exhaust in Operation @ Time of Testing. Note "N/A" if this system does not have Relief/Exhaust	Na
--	----

Fan Total Pressure Recorded	
-----------------------------	--

Fan VFD Speed (HZ)	Single speed
--------------------	--------------

OA Damper Position (Controls Output) include picture of damper position.	Na
--	----

Attach picture of each asset	Yes
------------------------------	-----

- [Open](#) File.jpg

Unit Operation

Heating	
---------	--

Cooling	
---------	--

Wash-Down Validation	
----------------------	--

Make, Model, and Serial Number:	
---------------------------------	--

Fan CFM:	
----------	--