



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-13-93 CC1 DRY INGREDIENTS	Status :	Submitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Appears fan was relocated to current position and power was never ran to motor.
<ul style="list-style-type: none"> • Open File.jpg 	
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan total pressure recorded.	No
Is Fan interlocked with any other asset? if so, list:	No. Should run same time as ef-5-93
When is fan used (application) and any specific time?	Heat evac in summertime