



Nestle (Mt Sterling, KY)

Project RFI Information

Issue Name :	MAU 2-96	Organization :	MAU 2-96
Status :	Pending	Assigned To :	National TAB - JOE HERTENSTEIN
Shared To :		Created :	Tyler Youells
Open :	05/11/2021 - Tyler Youells - National TAB	Description:	Unit has high discharge pressure and is only 1,800 cfm aprox. Unit has duct sock that is not fully expanded.

Project RFI File Details

- 1. [Open](#) File.jpg

Project RFI Response Details

- **05/27/2021 National TAB - JOE HERTENSTEIN**
 - FACILITIES TEAM TO REVIEW FOR MAINTENANCE
- **05/19/2021 National TAB - Alec Lewis**
 - May have a filter in the supply duct sock that could be clogged. Facilities mentioned they are a pain to change filters.
- **05/19/2021 National TAB - Alec Lewis**
 - Unit has been observed running all the time we have been on site.
- **05/12/2021 National TAB - Tyler Youells**
 - PICTURE OF DUCT SOCK.
 - 1. [Open](#) File.jpg
 - 2. [Open](#) File(1).jpg