



## Nestle (Mt Sterling, KY)

### CheckList Information

<b>Name :</b>	EF-2-14 / LOCKER ROOMS	<b>Status :</b>	NotSubmitted
<b>Assigned Organization :</b>	National TAB	<b>Asset :</b>	
<b>Requesting Organization :</b>	National TAB		

### CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	FAN has no belt and damage to the motor. Disconnect is off. And motor does not run when discount is on. Back housing of motor has fallen off and cooling fins have sheared from hitting it. Needs new motor
Attach picture of asset.	Yes
<ul style="list-style-type: none"> <li>• <a href="#">Open</a> File.jpg</li> <li>• <a href="#">Open</a> File(1).jpg</li> </ul>	
Fan total pressure recorded.	No
Is Fan interlocked with any other asset? if so, list:	No
When is fan used (application) and any specific time?	24/7 locker rooms
Make, Model, and Serial Number:	
Fan CFM:	