



Nestle (Mt Sterling, KY)

CheckList Information

Name :	MAU-6-04 / L8 OVEN AREA	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

MAU

Observe unit to ensure operational & no visual issue. If any comment. Note # of Duct Drops.	Make Greenheck Model:DGX-133-H42-DB Serial:04I03830 Current amp - 12.9A 30HP 460V 50.68A Avg fpm 1209 50" dia 16477 CFM
Unit Has Exhaust\Relief Fans & How Many. Note N/A if this does not apply.	NA
Verify outside air damper position & note approximate open amount (visual). Attached Picture	Unit short cycling air from space
<ul style="list-style-type: none"> • Open File.jpg 	
No Relief/Exhaust in Operation @ Time of Testing. Note "N/A" if this system does not have Relief/Exhaust	Unit is short cycling air from the space. Therefore unit is not supplying 100% of OA
Fan Total Pressure Recorded	-.27" fan suction
Fan VFD Speed (HZ)	NA single speed. Motor sheave is not adjustable.
OA Damper Position (Controls Output) include picture of damper position.	NA
Attach picture of each asset	Yes
<ul style="list-style-type: none"> • Open File.jpg 	

Unit Operation

Heating	
Cooling	
Wash-Down Validation	
Make, Model, and Serial Number:	Make Greenheck Model:DGX-133-H42-DB Serial:04I03830 Current amp - 12.9A 30HP 460V 50.68A Avg fpm 1209 50" dia

Fan CFM:

16477 CFM