



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-8-93 / ENGINE ROOM	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	No visual issues
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan total pressure recorded.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Is Fan interlocked with any other asset? if so, list:	No
When is fan used (application) and any specific time?	24/6 engine room
Make, Model, and Serial Number:	Unit data: Hartzell 63-44-LL3 Serial: 9302560-03-D 5 hp Motor 1800 rpm 460 6.6A Discharge 0.376"
Fan CFM:	[1]