



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF - 85 LINE 8 SHEETING	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Belt was loose. Tightened by NTAB no other issues so:-0.487"
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan total pressure recorded.	Yes
Is Fan interlocked with any other asset? if so, list:	Does not seem to be.
When is fan used (application) and any specific time?	Fan has been found on and off. There is likely a switch in the space
Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	
Make, Model, and Serial Number:	GREENHECK CUBE-300-20 SN:13668239 BALDOR 2HP 460 2.9 1755 RPM
Attach picture of asset.	
Fan CFM:	CFM: 6,709 SP:-0.487"