Comfort. Under control.

Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-22-93 OFFICE	**Status :**	Submitted
Assigned Organization :	National TAB	**Asset :**	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	2 diffusers
Attach picture of asset.	Yes
• Open File.jpg	
Fan total pressure recorded.	Yes
Is Fan interlocked with any other asset? if so, list:	No
When is fan used (application) and any specific time?	Office restrooms 24/7