



Nestle (Mt Sterling, KY)

CheckList Information

Name :	MAU-4-93 / WEST MAINTENANCE SHOP	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

MAU

Observe unit to ensure operational & no visual issue. If any comment. Note # of Duct Drops.	Stop switch is locked in position and disconnect is off.
<ul style="list-style-type: none"> Open File.jpg Open File(1).jpg 	
Unit Has Exhaust\Relief Fans & How Many. Note N/A if this does not apply.	
Verify outside air damper position & note approximate open amount (visual). Attached Picture	Na
No Relief/Exhaust in Operation @ Time of Testing. Note "N/A" if this system does not have Relief/Exhaust	Na
Fan Total Pressure Recorded	No unit not running
Fan VFD Speed (HZ)	
OA Damper Position (Controls Output) include picture of damper position.	
Attach picture of each asset	Yes
<ul style="list-style-type: none"> Open File.jpg 	
Unit Operation	
Heating	
Cooling	
Wash-Down Validation	
Make, Model, and Serial Number:	Unit data: Hartzell. 81-32-PL3 Serial: 9302562